

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/21/2017

Submitted Date:

08/22/2017

Document Number:

688300047**FIELD INSPECTION FORM**Loc ID 434879 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10399Name of Operator: NIGHTHAWK PRODUCTION LLCAddress: 1805 SHEA CENTER DR #290City: HIGHLANDS State: CO Zip: 80129**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Kosola, Jason		jason.kosola@state.co.us	COGCC EPS
Henkin, Joyce	(303) 407-9609	joycehenkin@nighthawkenergy.com	
Rezendes, Joe		JoeRezendes@nighthawkenergy.com	
Spear, Sam	(970) 554-1988	samspear@nighthawkenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159996	UIC Enhanced Recovery	AC	11/09/2016		-	Arikaree Creek Pilot Unit	AC

General Comment:

Spill (401369272) followup after stained soils were stockpiled by operator (see attached photos).

Inspected FacilitiesFacility ID: 159996 Type: UIC API Number: - Status: AC Insp. Status: AC**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688300087	Nighthawk Snowbird 16-15 Spill	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4234906