



Photo 1: View of the project area from the southwestern corner facing center.



Photo 2: View of the western portion of the project area from the southwestern corner of the well pad facing northward. Revegetation is progressing with grasses such as western wheatgrass (*Pascopyrum smithii*) and dropseed (*Sporobolus* sp.)



Photo 3: View of the southern portion of the project area from the southwestern corner of the well pad facing eastward.



Photo 4: View of musk thistles (*Carduus nutans*) within the project area.



Photo 5: View of erosional channel forming within the eastern portion of the project area.



Photo 6: View of another erosional channel forming within the eastern portion of the project area.



Photo 7: View of erosional downcutting and unstabilized soils near the well pad entrance facing eastward.