

Inspection Photos
Location Name: XTO Burkett #1-3
API: 05-067-06464



Stained soil beneath prime mover exhaust.



Secondary containment for lube oil container.

Inspection Photos
Location Name: XTO Burkett #1-3
API: 05-067-06464



Drip pan for prime mover engine.



Location BMP.