

Inspection Photos  
Location Name: Allard 30-8-5  
API: 05-057-06124



**Photo 1. Overview of wellhead portion of location taken at the entrance facing south.**



**Photo 2. Overview of battery portion of location taken at the entrance facing north.**

Inspection Photos  
Location Name: Allard 30-8-5  
API: 05-057-06124



**Photo 3. Weeds and vegetation in tank berm.**



**Photo 4. Fiberglass tank with no berm.**



Inspection Photos  
Location Name: Allard 30-8-5  
API: 05-057-06124



**Photo 5. Inadequate stormwater BMP and maintenance.**