

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/25/2017

Submitted Date:

08/29/2017

Document Number:

674901920

### FIELD INSPECTION FORM

Loc ID 325480 Inspector Name: Hughes, Jim On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**14 Number of Comments1 Number of Corrective Actions

- 
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Hixon, Logan	505-386-8018	logan_hixon@xtoenergy.com	<a href="#">SW EHS Tech</a>
Trobaugh, Robert	505-333-3185	robert_trobaugh@xtoenergy.com	<a href="#">SW Inspection Reports</a>
Fischer, Alex		alex.fischer@state.co.us	
Woolley, Jeff	505-333-3222	Jeff_Woolley@xtoenergy.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214860	WELL	PR	08/12/1992	GW	067-06464	BURKETT 1-3	EI

**General Comment:**

On August 25, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the XTO Burkett #1-3. For the most recent field inspection report of this facility, please refer to document #680601606.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Label and placard on lube oil container.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
Other	Pump Jack	<= 1 bbl	
Comment:	Stained soil underneath prime mover exhaust.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: <u>09/29/2017</u>
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Guard fencing, partial sound walls.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Stock panel fencing.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Ancillary equipment	# 2		corrective date
Comment:	Valve cans.		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

Type: Vertical Heated Separator	# 1		
Comment:	Combo unit with meter run.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 214860 Type: WELL API Number: 067-06464 Status: PR Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass			Material Handling And Spill Prevention	Pass	Drip pan for prime mover.
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for lube oil container.

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
On August 25, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the XTO Burkett #1-3. For the most recent field inspection report of this facility, please refer to document #680601606. Stained soil and gravel was observed beneath the prime mover exhaust.	hughesj	08/29/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901921	Inspection photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4239885">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4239885</a>