

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/29/2017

Submitted Date:

08/29/2017

Document Number:

689400165**FIELD INSPECTION FORM**
 Loc ID 324001 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Caerus Oil And Gas LLC		COGCC.inspections@caerusoilandgas.com	<a href="#">All Piceance inspections</a>
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211460	WELL	SI	06/01/2017	GW	045-07220	TEXACO FEE 6217	SI

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		Date: _____
Corrective Action:		

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Compressor and heat unit stored at tank battery.		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
LUBE OIL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:				Date:	

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	100 BBLS	STEEL AST		,

Comment:		Tank located next to pump jack.					
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
	Inadequate	Walls Insufficient	Base Insufficient	Inadequate			
Comment:		No containment around tank.					
Corrective Action:		Install berms or other secondary containment devices per Rule 906.d.(1).				Date: 09/29/2017	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	3	300 BBLS	HEATED STEEL AST		,		
Comment:							
Corrective Action:							
Date:							
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:							
Date:							
<u>Venting:</u>							
Yes/No	NO						
Comment:							
Corrective Action:							
Date:							
<u>Flaring:</u>							
Type							
Comment:							
Corrective Action:							
Date:							

**Inspected Facilities**Facility ID: 211460 Type: WELL API Number: 045-07220 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Last production on file was for 1 day in May 2017.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689400166	TEXACO FEE #6217	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4240124">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4240124</a>