

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/30/2017

Submitted Date:

08/30/2017

Document Number:

689300101

FIELD INSPECTION FORM

Loc ID 330688 Inspector Name: O'Donnell, Shaun On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10359
Name of Operator: WARD PETROLEUM CORPORATION
Address: 215 WEST OAK STREET #1000
City: FORT COLLINS State: CO Zip: 80521

Findings:

- 10 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
,		pgallagh@blm.gov	
Precup, Jim		james.precup@state.co.us	
,		birwin@fifthcreekenergy.com	
Gomez, Jason		jason.gomez@state.co.us	
,		marshall@wardpetroleum.com	
,		ssmith@fifthcreekenergy.com	
,		jeffd@wardpetroleum.com	
,		vkoebler@fs.fed.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251662	WELL	PR	12/01/2015	OW	123-19465	UPRC FEDERAL 23-3	SI

General Comment:

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Adequate		Date: _____
Corrective Action:			
Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil around pump jack motor in shed, stained soil at wellhead, stained soil in and around pump jack skid. See attached photos		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a.		Date: <u>09/30/2017</u>
Type	TRASH		
Comment:	Trash in pump jack motor shed southwest corner. See attached photos		
Corrective Action:	Comply with Rule 603.f .		Date: <u>09/09/2017</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Barbed wire		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Barbed wire		
Corrective Action:			Date:
Equipment:			
Type: Prime Mover			corrective date
	# 1		
Comment:	Ajax motor		
Corrective Action:			Date:
Type: Pump Jack			
	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line			
	# 1		
Comment:	1-1" unused/unmarked riser southwest of pump jack shed. Appears to be tied into scrub pot for fuel gas. See attached photos		

Corrective Action:	Date:
--------------------	-------

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		

Comment: [See API 123-19213 for equipment inventory](#)

Corrective Action:	Date:
--------------------	-------

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:

Corrective Action:	Date:
--------------------	-------

Venting:

Yes/No	NO	Date:	
Comment:			
Corrective Action:			Date:

Flaring:

Type		Date:	
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 251662 Type: WELL API Number: 123-19465 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689300102	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4240803