

Location

Overall Good:

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	APPROX 28' SOUND WALLS ON NORTH, EAST AND SOUTH END OF LOCATION FOR SOUND MITIGATION		
Corrective Action:			Date:

Equipment:			corrective date
Type:	#		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 447231 Type: WELL API Number: 123-43474 Status: XX Insp. Status: DG

Facility ID: 447232 Type: WELL API Number: 123-43475 Status: XX Insp. Status: DG

Facility ID: 447234 Type: WELL API Number: 123-43476 Status: XX Insp. Status: DG

Facility ID: 447235 Type: WELL API Number: 123-43477 Status: XX Insp. Status: DG

Complaint

Comment: [Complaint Received Aug 25, 2017](#)

Field Inspector Assigned: Jason E. Gomez

Complaint Received:

Date: 8-25-2017 Time 1000 Hrs

Contacted by Complaint Specialist per Complaint Response forms

Date: 8-25-2017 Time 1000 Hrs

Well Number#: Location #: 447233

Inspection Document #: 674200203

Nature of complaint: Noise/ Vehicle Tracking

Field Inspector Actions:

On 8-25-2017, I was contacted by complaint specialist Megan Adamczyk in reference to several complaints received by the COGCC about odor occurring in the Fort Lupton area of the Kerr McGee , Wagner location.

On 8-25-2017, I performed a complete site inspection of the Wagner location and the entrance to the lease road of the Wagner drilling pad. At the time of inspection, I observed a spud rig on the location performing drilling operation for Kerr McGee. I reviewed location records, which did not show any abnormal drilling conditions at the time of the noise complaints. At the time of the inspection Kerr McGee was in the process of repairing the vehicle tracking pad at the entrance of the location and a street sweeper was cleaning the county road.

I performed a noise study approx. 25' from the residence of the complaints south side of her home. During the sound study heavy truck traffic was entering the location to the west of the Wagner location contributing to the noise study. I attached this sound study to the inspection doc #67200203.

I contacted Anadarko and requested a sound study be run in attempt to compare with the study run by the COGCC.

All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action: _____ Date: _____

Well Drilling

Rig: Rig Name: _____ Pusher/Rig Manager: _____
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____

Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____

Multi-Well: _____ Disposal Location: _____

Comment: _____

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass			Vehicle Tracking	Pass	
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Compaction	Pass	Compaction	Pass	Covering Materials	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674200204	SOUND STUDY	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4241056
674200205	PHOTO OF SOUND STUDY TAKEN APPROX 25' FROM RESIDENCE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4241057