

Location

Lease Road:

	Type Access		
comment:	Trail off of county road		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:	Lease sign mounted to meter shed		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 205907 Type: WELL API Number: 009-06322 Status: PR Insp. Status: WK

Workover

Comment: PIONEER WIRELINE, DILLCO WATER SERVICE. MIRU PIONEER, RIH W/CIBP, SET AT 3218'. MIRU DILLCO, PUMP 80BBLS WATER, WELL WENT ON VACUUM. MIRU PIONEER, RIH W/CIBP, SET AT 1680'. MIRU DILLCO, PUMP 110BBLS WATER W/FLUID TO SFC. MIRU PIONEER, RIH W/GUN, PERF AT 1663'. RIH W/GUN, PERF 500'. BEGIN CEMENTING AT LATER DATE.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT