

Inspection Photos
Location Name: XTO Huber Lewis #2-33
API: 05-067-07794



Lube oil container with secondary containment.



Drip pot on load out line.

Inspection Photos
Location Name: XTO Huber Lewis #2-33
API: 05-067-07794



Location BMP.



Run on diversion ditch.