

Inspection Photos
Location Name: Alex Miller #1
API: 05-123-08976



Photo from prior inspection for comparison



Photo 1: Fence removed, bradenhead plumbed to surface.

Inspection Photos
Location Name: Alex Miller #1
API: 05-123-08976



Photo 2: Marked riser at SE corner