



**Photo 1: View of area documented in previous inspection with erosive channel, that is armored and stabilized at this time.**



**Photo 2: View of straw wattles placed along the eastern edge of the well pad, appear to be functioning at this time.**



**Photo 3: View of wattles where stormwater flows down the southeastern portion of the project area.**



**Photo 4: View of cobble-armored silt trap in the southern portion of the project area.**





**Photo 5: View of newly armored cobble-overflow channel in silt trap in the southern portion of the project area.**