

Inspection Photos
Location Name: Resler #22-27
API: 05-121-10345
Inspection Date: August 16, 2017



Photo 1 – Well sign attached to shed.



Photo 2 – Wellhead and uncontrolled weeds.

Inspection Photos
Location Name: Resler #22-27
API: 05-121-10345
Inspection Date: August 16, 2017



Photo 3 - Unlabeled 55-gallon drum lacking secondary containment and day tank beneath pumping unit with adequate secondary containment.



Photo 4 – Storage drum inside of shed with adequate secondary containment. Note: broken glass in background.

Inspection Photos
Location Name: Resler #22-27
API: 05-121-10345
Inspection Date: August 16, 2017




Photo 5 – Prime mover with broken glass inside of shed.



Photo 6 – Historical accumulation of asphaltic material outside of pump jack shed (1).

Inspection Photos
Location Name: Resler #22-27
API: 05-121-10345
Inspection Date: August 16, 2017



**Photo 7 - Historical accumulation of asphaltic material
outside of pump jack shed (2).**