

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/16/2017

Submitted Date:

09/01/2017

Document Number:

681700806

### FIELD INSPECTION FORM

Loc ID 317289 Inspector Name: Arauza, Steven On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 27635  
 Name of Operator: ENERGY SEARCH CO ADBA ENERGY SEARCH CO  
 Address: PO BOX 1896  
 City: EDWARDS State: CO Zip: 81632

**Findings:**

- 10 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
,		dnr_cogccengineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
237842	WELL	PR	02/19/2015	OW	121-10345	RESLER 22-27	EI

**General Comment:**

COGCC environmental inspection of orphan well. See FIR #681700805 for associated tank battery and pit complex. Operator's authorization to conduct oil and gas operations in the state of Colorado was terminated under COGCC Order 1V-636.

Production records have not been reported for subject well since February 2015. There are no MIT's on record for this well.

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Access road (two-track) is overgrown and can be difficult to locate.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	No COGCC emergency contact info on well sign. See photos.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Operator is out of business, so emergency contact info on well and battery signs is no longer valid.		
Corrective Action:			Date:
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Unlabeled 55-gallon drum at pumping unit lacks secondary containment.		
Corrective Action:			Date:
Type	TRASH		
Comment:	Broken glass inside of pump jack shed.		
Corrective Action:			Date:
Type	WEEDS		
Comment:	Uncontrolled weeds.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	Historical accumulation of asphaltic material underlying pump jack shed.		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Hog panel fence		
Corrective Action:			Date:
<b>Equipment:</b>			
			corrective date
Type: Ancillary equipment	# 1		
Comment:	Day tank at pump jack has adequate secondary containment. See photos.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	55-gallon drum inside of pump jack shed has adequate secondary containment. An oily rag was resting on top of drum on date of inspection.		

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 237842 Type: WELL API Number: 121-10345 Status: PR Insp. Status: EI

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681700835	Field Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4243057">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4243057</a>