

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/14/2017

Submitted Date:

09/01/2017

Document Number:

685100219

**FIELD INSPECTION FORM**

Loc ID 324630 Inspector Name: NEIDEL, KRIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10352  
Name of Operator: CM PRODUCTION LLC  
Address: 390 UNION BLVD SUITE 620  
City: LAKWOOD State: CO Zip: 80228

**Findings:**

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212200	WELL	SI	03/25/2013	OW	057-06093	MARGARET SPAULDING 11	EG
451743	SPILL OR RELEASE	AC	08/17/2017		-	SPILL/RELEASE POINT	EI

**General Comment:**

On August 14, 2017 COGCC Environmental Staff (Alex Fischer) conducted an inspection of CM Productions LLC, Lone Pine Field including: APIs 057-06011, 057-06097, 057-06009, 057-06070, 057-06115, 057-06127, 057-06012, 057-06093, 057-06273, 057-06031, 057-06047, 057-06108, 057-06021, 057-06112, 057-06057, 057-06100, 057-06116, 057-06095, 057-06062, 057-06069. the Production Facility area, and the Pit Complex Facility (Location ID: 324634, Pit Facility IDs 112265, 112266, 112267, 112268, 112269, 115241, and Land Application Facility ID 441982). The gate at the north entrance was locked. Weather was cloudy, and temps in the mid 70s at time of inspection. Cattle were grazing the lease. Water was observed in all the irrigation ditches. The Facility and Field are SI at this time. On Monday 8/14/2017, COGCC Environmental Staff, Kris Neidel inspected the Margaret Spaulding #11 well. Upon Arrival at 0900am it was observed that a 1" line, on tee below the stuffing box, was releasing water. The valve on the 1" line was immediately shut in, this stopped the release. COGCC staff walked around the location to determine path of the released water. It was observed that water was pooling on the pad, there was NO evidence that water had overtopped the location berm. NO sheen was observable on pooled water on pad. Water was pooled in the cellar. NO Free product was observable as a result of this spill. A blind plug assembly was installed in to prevent this same release from reoccurring. Photos are attached. Adjacent land is used for grazing however, there was no evidence that any livestock had been in contact with the released fluid (tracks, scat). Soil Samples will be taken to determine the magnitude of impact. Map of impacted area to follow.

**Inspected Facilities**

Facility ID: 212200 Type: WELL API Number: 057-06093 Status: SI Insp. Status: EG

Facility ID: 451743 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100220	photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4243122">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4243122</a>