



Photo 1: View of the project area from the southeastern corner facing center.



Photo 2: View of the southern portion of the project area from the southeastern corner facing westward. Revegetation is sparse and appears to be largely comprised of weeds such as chamomile (*Anthemis* sp.)



Photo 3: View of the northern portion of the project area from the northeastern corner of the well pad facing westward.



Photo 4: View of the eastern portion of the project area facing southward. Unused anchors in foreground do not appear needed.