

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/17/2017

Submitted Date:

09/05/2017

Document Number:

681700812**FIELD INSPECTION FORM**
 Loc ID 319813 Inspector Name: Arauza, Steven On-Site Inspection ☐ 2A Doc Num:
Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 27635
 Name of Operator: ENERGY SEARCH CO ADBA ENERGY SEARCH CO
 Address: PO BOX 1896
 City: EDWARDS State: CO Zip: 81632
Findings:

10 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201449	WELL	PR	02/19/2015	OW	001-06852	TSUZUKI 3	EI

General Comment:

COGCC environmental inspection of orphan well. Operator's authorization to conduct oil and gas operations in the state of Colorado was terminated under COGCC Order 1V-636.

Production has not been reported for subject well since August 2014. There are no MITs on record for this well.

Location					
Lease Road:					
Type	Access				
comment:	Access road is not maintained and difficult to locate.				
Corrective Action	L				Date:
Overall Good: <input type="checkbox"/>					
Signs/Marker:					
Type	WELLHEAD				
Comment:	Operator information at sign is covered and faded. No COGCC emergency contact info on well sign. See photos.				
Corrective Action:					Date:
Emergency Contact Number:					
Comment:	Operator is out of business, so emergency contact info on well and battery signs is no longer valid.				
Corrective Action:					Date:
Good Housekeeping:					
Type	WEEDS				
Comment:	Wind-blown weeds accumulating along fence. See photos.				
Corrective Action:					Date:
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment: <input type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	PUMP JACK				
Comment:	Chain link with barbed wire.				
Corrective Action:					Date:
Equipment:					
					corrective date
Type: Pump Jack	# 1				
Comment:	Localized, oil-stained soil/weeds/debris at wellhead. See photos.				
Corrective Action:					Date:
Type: Ancillary equipment	# 1				
Comment:	Small day tank at SE corner of pump jack lacks secondary containment device. See photos.				
Corrective Action:					Date:
Type: Prime Mover	# 1				
Comment:	Localized, oil-stained soil and oily rag beneath prime mover. See photos.				
Corrective Action:					Date:
Type: Deadman # & Marked	# 4				

Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	NOT IN USE: Uncapped 1" flowline east of pumping unit. See photos.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 201449 Type: WELL API Number: 001-06852 Status: PR Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681700837	Well sign.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4243817
681700838	Pump jack.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4243818
681700839	Wellhead.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4243819
681700840	Stains at prime mover.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4243820
681700841	Abandoned flowline riser.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4243821
681700842	Day tank.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4243822
681700843	Stains, weeds, and debris at wellhead (1)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4243823
681700844	Stains, weeds, and debris at wellhead (2)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4243824