

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401395408

Date Received:

09/07/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 39560
Name of Operator: TOP OPERATING COMPANY FDDB MURRAY J HERRING LTD
Address: 3609 S WADSWORTH BLVD STE 340
City: LAKEWOOD State: CO Zip: 80235

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>HERRING, PAUL</u>	<u>(303) 727-9915</u>	<u>paul.herring@topoperating.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 682402635
Inspection Date: 08/16/2017 FIR Submit Date: 08/21/2017 FIR Status: _____

Inspected Operator Information:

Company Name: TOP OPERATING COMPANY FDDB MURRAY J HERRING LTD Company Number: 39560
Address: 3609 S WADSWORTH BLVD STE 340
City: LAKEWOOD State: CO Zip: 80235

LOCATION - Location ID: 317999

Location Name: SCHNEIDER-62N67W Number: 25NENE County: _____
Qtrqtr: NENE Sec: 25 Twp: 2N Range: 67W Meridian: 6
Latitude: 40.114627 Longitude: -104.832501

FACILITY - API Number: 05-123-00 Facility ID: 317999

Facility Name: SCHNEIDER-62N67W Number: 25NENE
Qtrqtr: NENE Sec: 25 Twp: 2N Range: 67W Meridian: 6
Latitude: 40.114627 Longitude: -104.832501

CORRECTIVE ACTIONS:

1 CA# 94052

Corrective Action: Corrective Action (CA) #1 Revegetation activities shall be complete no later than 11/15/17. CA #2 Comply with the Pipeline/Flowline NTO and/or Reclamation Rule 1004.a. to remove (regardless of ownership) all equipment by 9/18/2017. CA #3 The following shall be performed by 9/18/17: Remove the meter shed equipment and pipe risers with other associated equipment; remove gravel from location and access road; perform compaction alleviation and recontour/re-grade access road. Ensure temporary stabilization controls are in place until revegetation activities can occur later in the Fall. See COGCC comments for additional compliance information regarding revegetation.

Date: 09/18/2017

Response: CA COMPLETED Date of Completion: 09/05/2017

Operator Comment: All flow lines and the meter house not owned by TOP Operating Co. were removed according to COGCC standards. Flowlines were capped below surface level. There is an operational gas meter operated by DCP on site.

Gravel was removed from the site.

At the request of the surface owner, TOP is not undertaking additional reclamation activities.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: All flow lines and the meter house not owned by TOP Operating Co. were removed according to COGCC standards. Flowlines were capped below surface level. There is an operational gas meter operated by DCP on site.

Gravel was removed from the site.

At the request of the surface owner, TOP is not undertaking additional reclamation activities.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Paul Herring

Signed: _____

Title: Landman

Date: 9/7/2017 3:15:56 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401397743	Letter from landowner
401397750	Pictures from location (risers buried)

Total Attach: 2 Files