

# Construction and Stormwater Inspection

September 7, 2017

Operator: BURLINGTON RESOURCES OIL & GAS LP- #26580

Location ID: 451622

Arapahoe County, CO

NWSW Section 1 T5S R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

**Inspection Photos**  
**Location Name: State Challenger 5-65 2-3 /3BYH**  
**Location ID: 451622**



**Photo 1.** Photo taken from the eastern location, facing Southwest. Construction operations are still underway. Disturbance areas outside of the well pad have been temporarily stabilized with equipment.



**Photo 2.** . Photo taken from the eastern location, facing Northwest. Construction operations are still underway. Disturbance areas outside of the well pad have been temporarily stabilized with equipment.

Inspection Photos  
Location Name: State Challenger 5-65 2-3 /3BYH  
Location ID: 451622



**Photo 3.** Photo taken from the eastern location, facing North. Photo taken of the access road coming into the location.



**Inspection Photos**  
**Location Name: State Challenger 5-65 2-3 /3BYH**  
**Location ID: 451622**



**Photo 4.** Photo taken from the southern location, facing West. Temporary Filtrexx BMP installed around the southern location. Cut slopes have been temporarily stabilized. It should be noted that equipment did not correctly track some cut slopes such that the grooves run perpendicular to the cut slopes. Operator will mulch and seed all disturbance area outside of the well pad. Perimeter ditch around well pad.



**Photo 5.** Photo taken from the western location, facing North. Temporary Filtrexx BMP installed around portions of the western location. Perimeter ditch around well pad.

**Inspection Photos**  
**Location Name: State Challenger 5-65 2-3 /3BYH**  
**Location ID: 451622**



**Photo 6.** Photo taken from the northern well pad, west access entrance to location, facing East. Culvert installed with a stabilized outlet area. Culvert installed in conjunction with the well pad perimeter ditch. Stormwater runoff is being directed to a sediment trap-see photo 7.



**Photo 7.** Photo taken from the northern location, facing North. Sediment trap construction underway.



## Inspection Photos

Location Name: State Challenger 5-65 2-3 /3BYH

Location ID: 451622



**Photo 8.** Photo taken from the east culvert area of the intermittent stream crossing, facing South. Operator In-Process of stabilizing culvert area. Operator shall ensure erosion and sediment controls are installed along access road portions to control and manage for sediment discharge.



**Photo 9.** Photo taken from the west culvert area of the intermittent stream crossing, facing North. Operator In-Process of stabilizing culvert area. Operator shall ensure erosion and sediment controls are installed along access road portions to control and manage for sediment discharge.