

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/08/2017

Submitted Date:

09/12/2017

Document Number:

682402741**FIELD INSPECTION FORM**

Loc ID 447902	Inspector Name: Binschus, Chris	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 4 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>10520</u> Name of Operator: <u>CRESCENT POINT ENERGY U.S. CORP</u> Address: <u>555 17TH STREET SUITE 1800</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				

Contact Information:

Contact Name	Phone	Email	Comment
Teren, Todd	(303) 308-6271	tteren@crescentpointenergy.com	
DelHiero, Chris		cdelhiero@crescentpointenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447900	WELL	XX	09/29/2016		123-43663	Shull Fed 9-59-31-1209CE	CI
447901	WELL	XX	09/29/2016		123-43664	Shull Fed 9-59-31-0508BE	CI
447903	WELL	XX	09/29/2016		123-43665	Shull Fed 9-59-31-2124CE2	CI
447904	WELL	XX	09/29/2016		123-43666	Shull Fed 9-59-31-0508CDE	CI
447905	WELL	XX	09/29/2016		123-43667	Shull Fed 9-59-31-1209AE	CI
447906	WELL	XX	09/29/2016		123-43668	Shull Fed 9-59-31-2124CE	CI
447907	WELL	XX	09/29/2016		123-43669	Shull Fed 9-59-31-2124BE	CI
447908	WELL	XX	09/29/2016		123-43670	Shull Fed 9-59-31-1209BE	CI

General Comment:

This is a follow-up construction and stormwater inspection to Field Inspection Report Document #682402637.

Inspected Facilities				
Facility ID: <u>447900</u>	Type: <u>WELL</u>	API Number: <u>123-43663</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447901</u>	Type: <u>WELL</u>	API Number: <u>123-43664</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447903</u>	Type: <u>WELL</u>	API Number: <u>123-43665</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447904</u>	Type: <u>WELL</u>	API Number: <u>123-43666</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447905</u>	Type: <u>WELL</u>	API Number: <u>123-43667</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447906</u>	Type: <u>WELL</u>	API Number: <u>123-43668</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447907</u>	Type: <u>WELL</u>	API Number: <u>123-43669</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447908</u>	Type: <u>WELL</u>	API Number: <u>123-43670</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION

Pass

Comment

Appears topsoil has been salvaged and stored along the southern perimeter of the well pad location.

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____ In Process

Comment

Topsoil has been temporarily stabilized with equipment for short-term stabilization.

The Operator shall consider both short and long-term stabilization BMPs when stabilizing topsoil stockpiles. Per Rule 1002, topsoil shall be stabilized and protected from degradation due to wind and water erosion. Per Rule 1002, BMPs to prevent weed establishment and to maintain soil microbial activity shall be implemented.

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Gravel	In Process			
<p>Comment: A temporary BMP (ditch) has been installed around the entire perimeter of the location. The south and west fill slopes appear to be temporarily stabilized, even though equipment has not properly tracked perpendicular to the slope. Water truck was observed at location mitigating fugitive dust from operations. As the previous inspection noted, the temporary BMP appears sufficient during initial pad construction. More permanent BMPs should be installed upon the completion of pad construction. A follow-up inspection will occur to ensure Operator has installed stormwater BMPs to meet Rule 1002.f. standards. Refer to the attached inspection photos for more details.</p>						
<p>Corrective Action:</p>						<p>Date: _____</p>
<p>Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682402742	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4249007