



Photo 1: View of the project area from the northwestern corner facing center. Sign is tipped over.



Photo 2: View of the northern portion of the project area from the northwestern corner facing eastward. Revegetation is progressing within the interim reclamation areas such as western wheatgrass (*Pascopyrum smithii*), crested wheatgrass (*Agropyron cristatum*), and intermediate wheatgrass (*Thinopyron intermedium*).



Photo 3: View of the southern portion of the project area from the southwestern corner facing eastward.



Photo 4: View of the western portion of the project area from the southwestern corner facing northward. Vegetation below fill slope is degraded and sparse.



Photo 5: View of area in the western portion of the project area where concentrated stormwater flow is eroding a channel here.



Photo 6: View of erosion occurring along the access road into a drainage. This area needs to be stabilized.



Photo 7: View of flowering and seeding musk thistles (*Carduus nutans*) within the project area.