

Inspection Photos
Location Name: Wells Ranch USX AA23-65-1HN Pad
API: 05-123-35337



Photo 1: Location, looking SE



Photo 2: Wellheads, looking SE

Inspection Photos

Location Name: Wells Ranch USX AA23-65-1HN Pad

API: 05-123-35337



Photo 3: Stained soil at wellhead



Photo 4: Stormwater erosion on NW side of location



Inspection Photos

Location Name: Wells Ranch USX AA23-65-1HN Pad

API: 05-123-35337



Photo 5: Stained soil in separator housing