

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/12/2017

Submitted Date:

09/12/2017

Document Number:

666803677

FIELD INSPECTION FORM

Loc ID 335157 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
 Name of Operator: VANGUARD OPERATING LLC
 Address: 5847 SAN FELIPE #3000
 City: HOUSTON State: TX Zip: 77057

Findings:

13 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292114	WELL	PR	05/20/2008	GW	045-14600	SPECIALTY 34A-21-692	PR
292945	WELL	PR	05/27/2008	GW	045-14819	SPECIALTY 34C-21-692	PR
292946	WELL	PR	05/23/2008	GW	045-14820	SPECIALTY 33C-21-692	PR
292947	WELL	PR	05/30/2008	GW	045-14821	SPECIALTY 44C-21-692	PR
292948	WELL	PR	08/11/2008	GW	045-14822	SPECIALTY 43A-21-692	PR
292949	WELL	PR	08/10/2008	GW	045-14823	SPECIALTY 43C-21-692	PR
292950	WELL	PR	07/31/2008	GW	045-14824	SPECIALTY 44A-21-692	PR
292951	WELL	PR	05/25/2008	GW	045-14825	SPECIALTY 33A-21-692	PR

General Comment:

[Shared facilities with location ID 335497](#)

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:


Venting:

Yes/No	YES		
Comment:	Bradenhead valves open		
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities										
Facility ID:	292114	Type:	WELL	API Number:	045-14600	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Plunger lift									
Corrective Action:							Date:			
Facility ID:	292945	Type:	WELL	API Number:	045-14819	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Plunger lift									
Corrective Action:							Date:			
Facility ID:	292946	Type:	WELL	API Number:	045-14820	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Plunger lift									
Corrective Action:							Date:			
Facility ID:	292947	Type:	WELL	API Number:	045-14821	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Plunger lift									
Corrective Action:							Date:			
Facility ID:	292948	Type:	WELL	API Number:	045-14822	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Plunger lift									
Corrective Action:							Date:			
Facility ID:	292949	Type:	WELL	API Number:	045-14823	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Plunger lift									
Corrective Action:							Date:			
Facility ID:	292950	Type:	WELL	API Number:	045-14824	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Plunger lift									
Corrective Action:							Date:			
Facility ID:	292951	Type:	WELL	API Number:	045-14825	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Plunger lift									
Corrective Action:							Date:			



Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Sediment Traps	Pass			
Berms	Pass					
		Rip Rap	Pass			
		Check Dams	Pass			
Gravel	Pass					
Ditches	Pass					
		Ditches	Pass			
		Culverts	Pass			
Seeding	In Process					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT