

Inspection Photos
Location Name: K Diamond Ranch 32-10
API: 05-081-07692



Photo 1. Overview of location taken at entrance facing north.

Inspection Photos
Location Name: K Diamond Ranch 32-10
API: 05-081-07692



Photo 2. 3 – 2” and 3 – 1” steel risers at 40.48653, -107.81559



Photo 3. 3 – 2” steel risers at 40.48669, -107.81572

Inspection Photos
Location Name: K Diamond Ranch 32-10
API: 05-081-07692



Photo 4. 1 -1" and 1 - 2" steel riser at 40.48676, -
107.81588



Photo 5. 1 -1" steel riser and 1 - 2" steel riser at
wellhead