

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER Estimated Spill Volume: 5

Comment: Inspection of Spill #401399579. Spill consisted of ~5bbl of pw from subsurface dump line between separator and 300bbl PW/cond AST. AST is within poly-lined steel SPCC. Line has been excavated and exposed. Excavated soils are stockpiled within poly-lined dirt berms near south end of pad. No petroleum contamination observed within excavation such as staining, odor or sheen on small pools of rainwater.

Corrective Action: Per F-19 COA, continue to assess nature and extent of contamination with excavation and or borings and confirmation soil samples. Remediate to Table 910-1 standards and provide documentation in another Supplemental F-19 if the next phase attains Table 910-1 compliance. If not submit an F-27 with detailed assessment and remediation plan. If landfarming contaminated soil is required it must also be approved by surfaceowner. Closure data must include a figure showing spill area with sample locations plus laboratory results Date: 10/27/2017

Reportable: YES GPS: Lat _____ Long _____
 Proximity to Surface Water: 400 Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690300055	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4251502