

AC 02-14 API# 05-071-08256

Date: September 14, 2017

Corrective Actions completed regarding COGCC FIR Document # 689900166



Photo 1: Facing west along the main access road. Installed road base and crowned the driving surface to establish sheet flow. Dominated the bar ditch to direct run off to the culvert inlet.



Photo 2: Facing down the road. Installed road base and crowned the driving surface to establish sheet flow. Dominated the bar ditch to receive run off.

AC 02-14 API# 05-071-08256

Date: September 14, 2017

Corrective Actions completed regarding COGCC FIR Document # 689900166



Photo 3: Facing further down the road to the southeast. Installed road base and crowned the driving surface to establish sheet flow. Dominated the bar ditch to receive run off.



Photo 4: Installed road base and crowned the driving surface to establish sheet flow.

AC 02-14 API# 05-071-08256

Date: September 14, 2017

Corrective Actions completed regarding COGCC FIR Document # 689900166



Photo 5: Facing west along the main access road adjacent to the well pad. Dominated the bar ditch to receive run off.



Photo 6: Facing east along the main access road, east of AC 02-14 well pad. Installed a water turn out to reduce the volume of run off flowing down the main road.