

**Inspection Photos**  
**Location Name: USX AE #21-99HZ**  
**API: 05-123-31033**



**Photo 1: Location, looking NE**



**Photo 2: Wellhead, looking NE**

**Inspection Photos**  
**Location Name: USX AE #21-99HZ**  
**API: 05-123-31033**



**Photo 3: Stained soil at wellhead**



**Photo 4: Stained soil at engine**