

Inspection Photos
Location Name: USX AE #21-12
API: 05-123-26704



Photo 1: Location, looking SW



Photo 2: Wellhead, looking NW

Inspection Photos
Location Name: USX AE #21-12
API: 05-123-26704



Photo 3: Unused equipment at wellhead



Photo 4: Stained soil at wellhead.