

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/12/2017

Submitted Date:

09/18/2017

Document Number:

685303751**FIELD INSPECTION FORM**Loc ID 325312 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**25 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Ray, Mandi	505-324-5122	mray@hilcorp.com	
Roland, Kandis		kroland@hilcorp.com	
Leonard, Mike		mike.leonard@state.co.us	
Trujillo, Etta		ettrujillo@hilcorp.com	
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Shorty, Priscilla		pshorty@hilcorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214542	WELL	PR	07/29/1997	GW	067-06145	ALLISON UNIT 59	PR

General Comment:[See link at end of report for path to downloadable pictures.](#)[Inspection report contains corrective action and comment. See Good Housekeeping, Equipment, and Interim Reclamation sections of report for additional details.](#)

Location			
Lease Road:			
Type	Access		
comment:	Dirt and gravel access road.		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Sign on tank fencing.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Sign on tank fencing. Sign still reflects Burlington Resources as the operator.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Operator contact information on wellhead sign.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Identified (5) unused risers, Flowline risers not LO/TO or marked are considered unused equipment.		
Corrective Action:	Comply with Rule 603.f. For unused, unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.		Date: 10/19/2017
Type	OTHER		
Comment:	Steel cable on N side of location beside power pole anchor.		
Corrective Action:	Remove cable to comply with Rule 603.f.		Date: 10/19/2017
Type	UNUSED EQUIPMENT		
Comment:	Disconnected equipment on S side of gas meter shed.		
Corrective Action:	Remove equipment to comply with Rule 603.f.		Date: 10/19/2017
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	Steel post and hog wire fencing.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Steel post and pole barrier.		
Corrective Action:			Date:

Type	OTHER		
Comment:	Steel riser - Steel post and pole barrier.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Group of (3) risers - Steel post and pole barrier.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Riser and valve - Steel post and pole barrier.		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Flow Line	# 2		
Comment:	In use - 2" steel line from wellhead tubing and casing to separator inlet. All points co-located. In use - 2" steel line from separator outlet to gas meter inlet. All points co-located.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 5		
Comment:	Not all deadmen not marked.		
Corrective Action:	Locate and mark all deadmen to comply with Rule 1003.a.		Date: 10/19/2017
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:		Date:	
Type: Flow Line	# 5		
Comment:	Not in use - 2" steel riser with valve and plug on W side of gas meter shed. (B) point unknown. Abandoned sales flowline? Not in use - 1/2" steel riser on W side of gas meter shed. Not in use - 4" steel riser with valve and bolted cap NW of gas meter shed. (B) point unknown. Not in use - 2" steel riser with valve and plug N side of gas meter shed. (B) point unknown. Not in use - 4" steel riser with valve and plug N side of gas meter shed. (B) point unknown. Not in use - 1/2" steel line with valve and plug N side of meter shed. (B) point unknown.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	Open Top		,	
Comment:	Steel open top 120 BBL tank with expanded metal top and earthen berms.					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	120 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities			
Facility ID: 214542	Type: WELL	API Number: 067-06145	Status: PR
Insp. Status: PR			
Producing Well			
Comment:	PR - Review of electronic well file indicates last submitted production report was Jun 2017.		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Rural residential properties with irrigated and dry land farming. There is little to no vegetation growing in interim reclamation area and N side has vehicle rutting.

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Fail

Comment Deadmen not marked.

Corrective Action Locate and mark all deadmen to comply with Rule 1003.a.

Date 10/19/2017

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Berms around produced water tank.

Comment: [Stormwater BMPs appear to be functioning at time of inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685303764	Inspection pictures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4253355