

On September 12, 2017, COGCC staff, Kris Neidel inspected the spill on the DAKA flowline (spill 401395060). The release point was observable as the excavation was still open. Some (lite) salt staining was observable in the excavation, it appeared to be recent and not indicative of an older or historic release. There was no other indication in the excavation that this spill had occurred previous to the reported date. Surface area that was impacted by release has been tilled; it is approximately 300' by 100' area. Some observable hydrocarbon stained soil has been tilled into the spill area. Required Action: remove any detected oil stained soil and haul to Landfarm. Visually stained soils should not be treated in place.



Spill area from upgrade



Spill area from upgrade



Spill area from upgrade



09.12.2017 13:02







Flowline, repair is observable















09.12.2017 13:05











09.12.2017 13:06