

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/14/2017

Submitted Date:

09/18/2017

Document Number:

685303755

FIELD INSPECTION FORM

Loc ID 322097 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100178
 Name of Operator: D J SIMMONS INC
 Address: P.O. BOX 1469
 City: FARMINGTON State: NM Zip: 87401

Findings:

- 33 Number of Comments
9 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Telecky, Barbara		btelecky@blm.gov	Durango
Rabinowitz, Daniel	970-385-1363	drabinow@blm.gov	Durango
Leonard, Mike		mike.leonard@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	COGCC

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208959	WELL	PR	03/01/2017	GW	033-06064	RANGER-FEDERAL 24-7	PR

General Comment:

[See link at end of report for path to downloadable pictures.](#)

[Inspection completed to inventory risers/flowlines and check compliance with May 2017 Flowline NTO.](#)

[Inspection report contains corrective actions and comment.](#)

Location			
Lease Road:			
Type	Access		
comment:	Dirt and gravel access road.		
Corrective ActionL		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Metal sign on gas meter run shed.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Labels directly on tank. No capacity label on any of the tanks or the open top tank.		
Corrective Action:	Install sign/label to comply with Rule 210.d.	Date:	11/18/2017
Type	BATTERY		
Comment:	Framed metal sign at tanks..		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Operator contact information on wellhead and tank battery sign. 505-326-3753 number goes to voicemail for the offices of D J Simmons.		
Corrective Action:		Date:	
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Concrete pad, pipe sections, fencing, and plywood stored on W side of steel building.		
Corrective Action:	Remove unused equipment to comply with Rule 603.f.	Date:	10/19/2017
Type	UNUSED EQUIPMENT		
Comment:	Pipe section behind open top tank.		
Corrective Action:	Remove pipe to comply with Rule 603.f.	Date:	10/19/2017
Type	UNUSED EQUIPMENT		
Comment:	Identified (16) unused risers/flowlines. Flowline risers not LO/TO or marked are considered unused equipment.		
Corrective Action:	Comply with Rule 603.f. For unused, unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.	Date:	10/19/2017
Type	OTHER		
Comment:	Impacted soil and gravel around base of wellhead. Less than a 5 gallon bucket clean up.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Impacted soil and gravel below tank 1 valve. Less than 5 gallon bucket clean up.		
Corrective Action:		Date:	
Type	UNUSED EQUIPMENT		
Comment:	Disconnected pipe in tank battery.		
Corrective Action:	Remove pipe to comply with Rule 603.f.	Date:	10/19/2017
Type	WEEDS		

Comment: Weeds and grass growing inside berms around fired production equipment.		Date:	
Corrective Action: Remove weeds to comply with Rule 603.f.		Date:	<u>09/29/2017</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment: Telemetry equipment.			
Corrective Action:		Date:	
Type: Other	# 1		
Comment: Steel building in NW corner of location.			
Corrective Action:		Date:	
Type: Flow Line	# 13		
Comment: In use - 2" steel line from wellhead tubing to separator inlet. All points co-located. In use - 2" steel line from separator outlet to gas meter inlet. All points co-located. In use - (2) 1" steel lines from separator oil and water outlets to tank battery. All point. In use - (3) 2" steel risers com out of ground at separator and go back into ground. (B) and (C) points unknown. Unused - (3) 2" steel risers at front of separator. (B) point unknown. Unused - 2" steel riser on N side of separator. (B) point unknown. In use - 1" steel line horseshoes on N side of separator. (B) and (C) points unknown. Unused - 2" steel riser between separator and gas meter shed. (B) point unknown.			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment: Not all dead men marked.			
Corrective Action: Locate and mark all deadmen to comply with Rule 1003.a.		Date:	<u>10/19/2017</u>
Type: Flow Line	# 9		
Comment: W end of location in and around steel building. In use - 4" line horseshoes above ground. (b) and (C) points unknown. Not in use - 1" steel riser. Not in use - 2" steel riser. Not in use - Off SW corner of building. 4" steel riser tied into above ground 8" steel line. (B) point unknwn. Not in use - Off SW corner of building. (2) 2" steel risers tied into above ground 8" steel line. (B) points unknown. Not in use - Inside building. (2) 1' steel risers. Not in use - Inside building. 2" steel riser.			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: Wellhead.			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 8		
Comment:	<p>In use - (2) 2" steel lines come out of the ground between separator and meter run shed. (B) and (C) points unknown. In use - (2) 2" steel risers come out of the ground at meter run shed. (B) and (C) points unknown. Not in use - (3) 2" steel risers inside tank battery. Tank equalizer line. In use - 1" steel riser inside tank battery. (B) point unknown.</p>		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		
Comment:	Above ground steel 210 BBL tank with earthen berms.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	210 BBLs
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Weed and grass patches noted growing inside berms.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		
Comment:	Open top tank with wildlife netting coveing tank. No capacity label. Earthen berms. Tank over half full.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	UNKNOWN
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berms are becoming weathered.			

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	3	400 BBLs	STEEL AST			
Comment: Above ground steel 400 BBL tanks with earthen berms.						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Weeds and grass patches noted growing inside berms.				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 208959 Type: WELL API Number: 033-06064 Status: PR Insp. Status: PR

Producing Well

Comment: [PR - Review of electronic well file indicates last reported production was July 2017 with production numbers of 357/2140.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Location on ridge with canyon to the N and forest area to S. Vegetation consisting of Juniper and Pinion Pines, Sage Brush, and Grasses.

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment

Corrective Action

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment

Corrective Action

Date _____

1002c. PROTECTION OF SOILS _____

Comment

Corrective Action

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment

Corrective Action

Date _____

1003a. Waste and Debris removed? Pass

Comment

Corrective Action

Date _____

Unused or unneeded equipment onsite? Pass

Comment

Corrective Action

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment

Corrective Action

Date _____

Guy line anchors marked? Fail

Comment Not all deadmen marked.

Corrective Action Locate and mark all deadmen to comply with Rule 1003.a.

Date 10/19/2017

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			
Berms	Pass	Compaction	Pass	Material Handling And Spill Prevention	Fail	
Gravel	Pass					

Comment: [55 gallon drums with fluids stored on location with no spill prevention.](#)

Corrective Action: [Install or repair required BMPs to comply with 1002.f.](#)

Date: 10/19/2017

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685303769	Inspection pictures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4253590