

- Cross Canyon Unit 1
- 05-033-06012



Photo 1: Wellhead sign. Previous inspection.

- Cross Canyon Unit 1
- 05-033-06012



Photo 2: Wellhead sign.

- Cross Canyon Unit 1
- 05-033-06012



**Photo 3: 1 of 3 pieces of cable, thistle, and vine weed.
Previous inspection.**

- Cross Canyon Unit 1
- 05-033-06012



Photo 4: 1 of 3 pieces of cable, thistle, and vine weed.

- Squaw Canyon - Federal 2
- 05-033-06045



Photo 5: Thistle. Previous inspection.

- Cross Canyon Unit 1
- 05-033-06012



Photo 6: Thistle.

- Cross Canyon Unit 1
- 05-033-06012



**Photo 7: Line into meter and low point stub up and valve.
Previous inspection**

- Cross Canyon Unit 1
- 05-033-06012



Photo 8: Line into meter and low point stub up and valve.

- Cross Canyon Unit 1
- 05-033-06012



Photo 9: Storm water erosion channel off front of production tank berm. Previous inspection.

- Cross Canyon Unit 1
- 05-033-06012



Photo 10: Storm water erosion channel off front of production tank berm.

- Cross Canyon Unit 1
- 05-033-06012



Photo 11: Stormwater flow coming down access road grade at entrance. Current inspection.

- Cross Canyon Unit 1
- 05-033-06012



Photo 12: Erosion channel off west side of location. Current inspection.

- Cross Canyon Unit 1
- 05-033-06012



Photo 13: Erosion channel on SW corner beside carport shelter. Current inspection.

- Cross Canyon Unit 1
- 05-033-06012



Photo 14: Erosion channel on SW corner along separator berms. Current inspection.