

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/15/2017

Submitted Date:

09/18/2017

Document Number:

685303759**FIELD INSPECTION FORM**Loc ID 322090 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100178Name of Operator: D J SIMMONS INCAddress: P.O. BOX 1469City: FARMINGTON State: NM Zip: 87401**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments4 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Rabinowitz, Daniel	970-385-1363	drabinow@blm.gov	Durango
Leonard, Mike		mike.leonard@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Telecky, Barbara		btelecky@blm.gov	Durango

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208908	WELL	PR	03/01/2017	GW	033-06012	CROSS CANYON UNIT 1	PR

General Comment:[See link at end of report for path to downloadable pictures.](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	In use - Steel 2" line from separator outlet to low point and gas meter inlet. All points on location. 37.620141/-108.979722 from scout card. Low point is stubbed up at gas meter house with swedge and 1" valve on top of line. Line has a return to blow down/clean out liquids from line. Valve not locked out and tagged. NTO required this to be completed by May 30, 2017. Flowline risers not LO/TO or marked are considered unused equipment. Corrective action not completed. Corrective action date remains the same to document days of noncompliance.		
Corrective Action:	Comply with Rule 603.f. For unused, unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.	Date:	05/30/2017
Type	WEEDS		
Comment:	S/SE perimeter has thistle infestation and vine weed spreading out onto location. Corrective action not completed. Corrective action date remains the same to document days of noncompliance.		
Corrective Action:	Remove and treat thistle/vine weeds to prevent recurrence to comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	07/02/2017
Type	DEBRIS		
Comment:	Pieces of steel 1" cable have surfaced in three places on location. Corrective action not completed. Cable has surfaced in additional places dur to recent storm events.		
Corrective Action:	Remove steel cable to comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	07/22/2017

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	208908	Type:	WELL	API Number:	033-06012	Status:	PR	Insp. Status:	PR

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Fail	Compaction	Pass	Material Handling And Spill Prevention	Pass	Berms around production tank.

Comment: Erosion channel off SE side of location just off front berm for produced water tank. Channel is 4"-6" deep and 4"-8" wide. Corrective action not complete. Corrective action date remains the same to document days of noncompliance.

Corrective Action: Install or repair required BMPs to comply with Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 07/22/2017

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685303773	Previous and current inspection pictures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4254082