

Inspection Photos



Photo 1. Facing southeast along the steep grade of the access road. Stormwater issues have been repaired.

Inspection Photos



Photo 2. Facing southeast along the access road. This area was graded but does not appear to have much gravel. Stormwater issues may be more susceptible in this area.

Inspection Photos



Photo 3. The oil on the engine skid was cleaned up.

Inspection Photos



Photo 4. Facing northwest along the main road in Big Bingham Canyon. There are stormwater issues along the main road.