

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/18/2017

Submitted Date:

09/20/2017

Document Number:

689900228**FIELD INSPECTION FORM**
 Loc ID 308026 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Harrison, Lyndon		lyndon_harrison@xtoenergy.com	
Trujillo, Irwin		irwin_trujillo@xtoenergy.com	
Fitzgerald, Edie		Edie_Fitzgerald@xtoenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260242	WELL	TA	06/20/2016	GW	071-07408	APACHE CANYON 02-16V	RI

**General Comment:**[This is a Follow Up Inspection](#)

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Seeding	Pass	Ditches	Pass			

Comment: Stormwater erosion issues were repaired along the main road near the location. Gravel was applied to portions of the road. The road and side ditches were regraded. There are signs of erosion beginning to occur from a recent storm event at the access road where stormwater is directed accross the road. As noted in the previous inspection, a culvert may need to be installed to properly divert stormwater. See Attached Photos

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689900229	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4255799">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4255799</a>