

Inspection Photos


Location Name: Valcar USX A 3-14

API #: 05-123-24596

Location ID: 306406



Wellheads looking east, weeds need to be controlled



Wellhead sign showing incorrect information/disconnected emergency contact information



Inspection Photos

Location Name: Valcar USX A 3-14

API #: 05-123-24596

Location ID: 306406



Battery looking south, weeds need to be controlled



Battery looking north, weeds need to be controlled



Inspection Photos

Location Name: Valcar USX A 3-14

API #: 05-123-24596

Location ID: 306406



Access road from battery to wellhead looking east. Weeds need to be controlled

