

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/20/2017

Submitted Date:

09/21/2017

Document Number:

685303775**FIELD INSPECTION FORM**Loc ID 333605 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Roland, Kandis		kroland@hilcorp.com	
Trujillo, Etta		ettrujillo@hilcorp.com	
Ray, Mandi	505-324-5122	mray@hilcorp.com	
Shorty, Priscilla		pshorty@hilcorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214835	WELL	PR	06/01/2012	GW	067-06439	MCCULLOGH 1	PR

General Comment:[See link at end of report for path to downloadable pictures.](#)[Inspection report contains corrective action and comment.](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

DEBRIS

Comment: Rolled up fencing behind gas meter shed.

Corrective Action: Remove fencing to comply with Rule 603.f.

Date: 10/22/2017

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	214835	Type:	WELL	API Number:	067-06439	Status:	PR	Insp. Status:	PR

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Gravel	Pass			
Berms	Pass	Compaction	Pass			
Gravel	Fail					
Compaction	Fail	Culverts	Pass	Material Handling And Spill Prevention	Pass	Berms around production tank battery.

Comment: Large erosion channel 8"-18" deep and 16"-24" wide in cut slope corner behind tank battery. Erosion channel 4"- 12" deep and 8"-12" wide has cut into fill slope carrying stormwater and sediment down face of fill slope and off location.

Corrective action not completed. Repairs were not adequate to manage stormwater. Additional erosion channels noted in cut and fill slopes.

Corrective Action: Install or repair required BMPs to comply with Rule 1002.f.

Date: 10/22/2017

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685303780	Inspection pictures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4256635