

Inspection Photos
Location Name: Dittmer KE Pad
API: 05-123-43441



Photo 1: Location, looking S



Photo 2: Wellheads, looking SW

Inspection Photos
Location Name: Dittmer KE Pad
API: 05-123-43441



Photo 3: 300 bbl tank lacking safety placarding



Photo 4: Stained soil in tank battery

Inspection Photos
Location Name: Dittmer KE Pad
API: 05-123-43441



Photo 5: Stained soil at crude oil loadout.



Photo 6: Stained soil at Wellheads on W side.

Inspection Photos
Location Name: Dittmer KE Pad
API: 05-123-43441



Fire damage photo



Fire damage photo

Inspection Photos
Location Name: Dittmer KE Pad
API: 05-123-43441



Fire damage photo



Fire damage photo

Inspection Photos
Location Name: Dittmer KE Pad
API: 05-123-43441



Fire damage photo



Fire damage photo

Inspection Photos
Location Name: Dittmer KE Pad
API: 05-123-43441



Fire damage photo



Fire damage photo

Inspection Photos
Location Name: Dittmer KE Pad
API: 05-123-43441



Fire damage photo

