



Photo 1: View of the northern portion of the project area from the northeastern corner facing westward. Equipment in the mid-ground needs to be removed. Project area needs to be reclaimed to COGCC's 1004 final reclamation rules.



Photo 2: View of the project area from the northeastern corner facing southwestward. Metal pipe connection needs to be removed.



Photo 3: View of the southern portion of the project area from the northeastern corner facing southward.



Photo 4: View of erosional channel forming within the western portion of the project area.



Photo 5: View of rig anchor still present within the project area. All rig anchors need to be removed.



Photo 6: View of riser near the entrance to the well pad needing to be removed.



Photo 7: View of approximately 0.15 acre area south of the well pad that needs reclamation.