

Inspection Photos
Location Name: McCallum Unit 60
API: 05-057-06041



Photo 1. Overview of location taken at entrance facing northeast.

Inspection Photos
Location Name: Stover Federal 9-12 1D
API: 05-081-07825



Photo 1. Cuttings stored on location.



Photo 2. Overview of location taken at entrance facing south.

Inspection Photos
Location Name: Spetter 5-8
API: 05-081-06548



Photo 4. Tank with no label and no berm. Container with no secondary containment next to tank.



Photo 5. Example of erosion occurring on west side of location.