

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/12/2017

Submitted Date:

09/18/2017

Document Number:

685100255

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: NEIDEL, KRIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**  
 OGCC Operator Number: 8960  
 Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY  
 Address: 410 17TH STREET SUITE #1400  
 City: DENVER State: CO Zip: 80202

**Findings:**  
 1 Number of Comments  
 1 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Dodek, Brian	720-225-6653	BDodek@bonanzacrk.com	
Fischer, Alex		alex.fischer@state.co.us	
Luke Kelly		Lkelly@bonanzacrk.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452051	SPILL OR RELEASE	AC	09/18/2017		-	DAKLAK Flowline	EI

**General Comment:**  
 On September 12, 2017, COGCC staff, Kris Neidel inspected the spill on the DAKA flowline (spill 401395060). The release point was observable as the excavation was still open. Some (lite) salt staining was observable in the excavation, it appeared to be recent and not indicative of an older or historic release. There was no other indication in the excavation that this spill had occurred previous to the reported date. Surface area that was impacted by release has been tilled; it is approximately 300' by 100' area. Some observable hydrocarbon stained soil has been tilled into the spill area. Required Action: remove any detected oil stained soil and haul to Landfarm. Visually stained soils should not be treated in place.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>					
Type	Area	Volume			
PW/CO	Flow Line	>= 5 bbls			
Comment: <input type="text"/>					
Corrective Action: <b>remove any detected oil stained soil and haul to Landfarm. Visually stained soils should not be treated in place.</b>				Date:	<u>09/25/2017</u>

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

**Flaring:**

Type	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

**Inspected Facilities**Facility ID: 452051 Type: SPILL OR API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401406408	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4253593">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4253593</a>
685100256	photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4253589">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4253589</a>