

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/12/2017

Submitted Date:

09/18/2017

Document Number:

685303751**FIELD INSPECTION FORM**Loc ID 325312 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**25 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Ray, Mandi	505-324-5122	mray@hilcorp.com	
Roland, Kandis		kroland@hilcorp.com	
Leonard, Mike		mike.leonard@state.co.us	
Trujillo, Etta		ettrujillo@hilcorp.com	
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Shorty, Priscilla		pshorty@hilcorp.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214542	WELL	PR	07/29/1997	GW	067-06145	ALLISON UNIT 59	PR

**General Comment:**[See link at end of report for path to downloadable pictures.](#)[Inspection report contains corrective action and comment. See Good Housekeeping, Equipment, and Interim Reclamation sections of report for additional details.](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Dirt and gravel access road.		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign on tank fencing. Sign still reflects Burlington Resources as the operator.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Sign on tank fencing.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Operator contact information on wellhead sign.		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Identified (5) unused risers, Flowline risers not LO/TO or marked are considered unused equipment.		
Corrective Action:	Comply with Rule 603.f. For unused, unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.		Date: 10/19/2017
Type	OTHER		
Comment:	Steel cable on N side of location beside power pole anchor.		
Corrective Action:	Remove cable to comply with Rule 603.f.		Date: 10/19/2017
Type	UNUSED EQUIPMENT		
Comment:	Disconnected equipment on S side of gas meter shed.		
Corrective Action:	Remove equipment to comply with Rule 603.f.		Date: 10/19/2017
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Steel post and pole barrier.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Riser and valve - Steel post and pole barrier.		
Corrective Action:			Date:

Type	OTHER		
Comment:	Group of (3) risers - Steel post and pole barrier.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Steel post and hog wire fencing.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Steel riser - Steel post and pole barrier.		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Flow Line	# 5		
Comment:	Not in use - 2" steel riser with valve and plug on W side of gas meter shed. (B) point unknown. Abandoned sales flowline? Not in use - 1/2" steel riser on W side of gas meter shed. Not in use - 4" steel riser with valve and bolted cap NW of gas meter shed. (B) point unknown. Not in use - 2" steel riser with valve and plug N side of gas meter shed. (B) point unknown. Not in use - 4" steel riser with valve and plug N side of gas meter shed. (B) point unknown. Not in use - 1/2" steel line with valve and plug N side of meter shed. (B) point unknown.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:	In use - 2" steel line from wellhead tubing and casing to separator inlet. All points co-located. In use - 2" steel line from separator outlet to gas meter inlet. All points co-located.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 5		
Comment:	Not all deadmen not marked.		
Corrective Action:	Locate and mark all deadmen to comply with Rule 1003.a.		Date: 10/19/2017
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	Open Top		,	
Comment:	Steel open top 120 BBL tank with expanded metal top and earthen berms.					
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	120 BBLS	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	214542	Type:	WELL	API Number:	067-06145	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR - Review of electronic well file indicates last submitted production report was Jun 2017.								
Corrective Action:								Date:	

--	--	--	--	--	--	--	--	--	--

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: Rural residential properties with irrigated and dry land farming. There is little to no vegetation growing in interim reclamation area and N side has vehicle rutting.

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? Fail

Comment Deadmen not marked.

Corrective Action Locate and mark all deadmen to comply with Rule 1003.a.

Date 10/19/2017

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Berms around produced water tank.
Gravel	Pass	Gravel	Pass			

Comment: [Stormwater BMPs appear to be functioning at time of inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401406125	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4253361">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4253361</a>
685303764	Inspection pictures.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4253355">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4253355</a>