

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/15/2017

Submitted Date:

09/18/2017

Document Number:

685303759

FIELD INSPECTION FORM

Loc ID 322090 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100178
Name of Operator: D J SIMMONS INC
Address: P.O. BOX 1469
City: FARMINGTON State: NM Zip: 87401

Findings:

- 9 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Telecky, Barbara		btelecky@blm.gov	Durango
Rabinowitz, Daniel	970-385-1363	drabinow@blm.gov	Durango
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208908	WELL	PR	03/01/2017	GW	033-06012	CROSS CANYON UNIT 1	PR

General Comment:

[See link at end of report for path to downloadable pictures.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	S/SE perimeter has thistle infestation and vine weed spreading out onto location. Corrective action not completed. Corrective action date remains the same to document days of noncompliance.		
Corrective Action:	Remove and treat thistle/vine weeds to prevent recurrence to comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	07/02/2017
Type	UNUSED EQUIPMENT		
Comment:	In use - Steel 2" line from separator outlet to low point and gas meter inlet. All points on location. 37.620141/-108.979722 from scout card. Low point is stubbed up at gas meter house with swedge and 1" valve on top of line. Line has a return to blow down/clean out liquids from line. Valve not locked out and tagged. NTO required this to be completed by May 30, 2017. Flowline risers not LO/TO or marked are considered unused equipment. Corrective action not completed. Corrective action date remains the same to document days of noncompliance.		
Corrective Action:	Comply with Rule 603.f. For unused, unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.	Date:	05/30/2017
Type	DEBRIS		
Comment:	Pieces of steel 1" cable have surfaced in three places on location. Corrective action not completed. Cable has surfaced in additional places dur to recent storm events.		
Corrective Action:	Remove steel cable to comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	07/22/2017

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 208908 Type: WELL API Number: 033-06012 Status: PR Insp. Status: PR

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail	Compaction	Pass	Material Handling And Spill Prevention	Pass	Berms around production tank.
Gravel	Pass	Gravel	Pass			

Comment: Erosion channel off SE side of location just off front berm for produced water tank. Channel is 4"-6" deep and 4"-8" wide. Corrective action not complete. Corrective action date remains the same to document days of noncompliance.

Corrective Action: Install or repair required BMPs to comply with Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 07/22/2017

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401406902	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4254084
685303773	Previous and current inspection pictures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4254082