

COGCC conducted an inspection of the Wells Ranch USX AA23 location (Location ID 429615) on September 12, 2017 (Document 684904341). During that inspection, COGCC made the following observations:

1. Equipment: Stained soil in separator housing. Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.
2. Equipment: Stained soil at wellhead. Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.
3. Storm Water: Stormwater erosion on NW side of location. Install or repair required BMPs per Rule 1002.f.

Name: Wells Ranch USX AA23

Location ID: 429615

COGCC conducted an inspection of the Wells Ranch USX AA23 location (Location ID 429615) on September 12, 2017 (Document 682402391). During that inspection, COGCC made the following observations:

2. Equipment: Stained soil at wellhead. Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

COGCC – 9/12/17



Photo 3: Stained soil at wellhead

Noble Energy – 9/20/17



Photo NBL1. The equipment was repaired and the stained soil was removed.

Location ID: 429615

COGCC conducted an inspection of the Wells Ranch USX AA23 location (Location ID 429615) on September 12, 2017 (Document 682402391). During that inspection, COGCC made the following observations:

3. Storm Water: Stormwater erosion on NW side of location. Install or repair required BMPs per Rule 1002.f.

COGCC – 9/12/17



Photo 4: Stormwater erosion on NW side of location

Noble Energy – 9/20/17



Photo NBL2. Erosion was repaired and new BMPs were installed

Name: Wells Ranch USX AA23

Location ID: 429615

COGCC conducted an inspection of the Wells Ranch USX AA23 location (Location ID 429615) on September 12, 2017 (Document 682402391). During that inspection, COGCC made the following observations:

1. Equipment: Stained soil in separator housing. Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

COGCC – 9/12/17



Photo 5: Stained soil in separator housing

Noble Energy – 9/20/17



Photo NBL3. The equipment was repaired and the stained soil was removed.