

**Inspection Photos**  
**Location Name: Lilli Unit #2-8**  
**API: 05-123-13638**



**Photo 1: Location, looking NE**



**Photo 2: Wellhead, looking E**

**Inspection Photos**  
**Location Name: Lilli Unit #2-8**  
**API: 05-123-13638**



**Photo from prior inspection for comparison**



**Photo 3: Stained soil removed**



**Inspection Photos**  
**Location Name: Lilli Unit #2-8**  
**API: 05-123-13638**



**Photo from prior inspection for comparison**



**Photo 4: Stained soil being remediating**

**Inspection Photos**  
**Location Name: Lilli Unit #2-8**  
**API: 05-123-13638**



**Photo from prior inspection for comparison**



**Photo 3: Low berms at tank battery**



**Inspection Photos**  
**Location Name: Lilli Unit #2-8**  
**API: 05-123-13638**



**Photo from prior inspection for comparison**



**Photo 5: Stormwater erosion at location, between treater and battery.**