

Inspection Photos
Location Name: Hoffman #34-10
API: 05-123-20097



Photo 1: Location, looking SE



Photo 2: Wellhead, looking NE

Inspection Photos
Location Name: Hoffman #34-10
API: 05-123-20097



Photo 3: Gap in mesh on open top skim



Photo 4: Stained weed debris at NW corner of southern pit

Inspection Photos
Location Name: Hoffman #34-10
API: 05-123-20097



Photo 5: Oily weed debris in between pits



Photo 6: Weeds in northern pit

Inspection Photos
Location Name: Hoffman #34-10
API: 05-123-20097



Photo 7: Stained soil, oily fluid at pump jack



Photo 8: Stained soil, oily fluid at pump jack

Inspection Photos
Location Name: Hoffman #34-10
API: 05-123-20097



Photo 9: Stained soil, oily fluid at pump jack



Photo 10: Stained soil at ajax engine

Inspection Photos
Location Name: Hoffman #34-10
API: 05-123-20097



Photo 11: Stained soil at ajax exhaust