

Inspection Photos
Location Name: Critter Creek #3-04H
API: 05-123-31973



Photo 1: Location looking SW

Photo 2: Wellhead, looking E

Inspection Photos
Location Name: Critter Creek #3-04H
API: 05-123-31973



Photo 3: Tank stenciling is for prior operator.



Photo 4: Unused pipe at wellhead.

Inspection Photos
Location Name: Critter Creek #3-04H
API: 05-123-31973



Photo 5: Stormwater erosion on S side of location



Photo 6: Stormwater erosion on S side of location