

- Padgett 32 – 6 4 - 2
- 05-067-08660



Photo 1: Wellhead sign.

- Padgett 32 – 6 4 - 2
- 05-067-08660



Photo 2: Wellhead sign.

- Padgett 32 – 6 4 - 2
- 05-067-08660



Photo 3: Unused riser/flowline at 4 - 2 wellhead.

- Padgett 32 – 6 4 - 2
- 05-067-08660



Photo 4: Unused riser/flowline at 4 – 2 wellhead.

- Padgett 32 – 6 4 - 2
- 05-067-08660



Photo 5: Unused riser/flowline at 4 – 2 separator.

- Padgett 32 – 6 4 - 2
- 05-067-08660



Photo 6: (3) unused riser/flowline behind 4 – 2 separator.

- Padgett 32 – 6 4 - 2
- 05-067-08660



Photo 7: Impacted soil and gravel at wellhead.

- Padgett 32 – 6 4 - 2
- 05-067-08660



Photo 8: Unused riser/flowlines by 4 – 4 wellhead.

- Padgett 32 – 6 4 - 2
- 05-067-08660



Photo 9: Unused riser/flowlines by 4 – 4 separator.

- Padgett 32 – 6 4 - 2
- 05-067-08660



Photo 10: Sediment plume from stormwater run on behind production equipment..

- Padgett 32 – 6 4 - 2
- 05-067-08660



Photo 11: Erosion channel carrying stormwater and sediment into production area.

- Padgett 32 – 6 4 - 2
- 05-067-08660



Photo 12: Erosion channel off SE corner of location.

- Padgett 32 – 6 4 - 2
- 05-067-08660



Photo13: Full culvert at entrance to location.

- Padgett 32 – 6 4 - 2
- 05-067-08660



Photo 14: Unused riser/flowline just outside entry to location.