

Inspection Photos
Location Name: McIntyre 1-3 ST
API: 05-081-06608



Photo 1. Overview of location taken at entrance facing northeast.



Photo 2. Frack tanks and tubing stored on location.

Inspection Photos
Location Name: McIntyre 1-3 ST
API: 05-081-06608



Photo 3. Stained soil at wellhead.



Photo 4. Close-up of stained soil at wellhead.

Inspection Photos
Location Name: McIntyre 1-3 ST
API: 05-081-06608



Photo 5. Partially covered rathole with fluid present.



Photo 6. Vegetation growing on and in berm.

Inspection Photos
Location Name: McIntyre 1-3 ST
API: 05-081-06608



Photo 7. Gauge hatches open on both tanks.



Photo 8. Stained soil on location.