

Inspection Photos



Photo 1. Facing east at the beginning of the access road. Contractor was preparing to install tracking pad. Operator must ensure tracking pad is installed to prevent sediment tracking onto county road.

Inspection Photos



Photo 2. Facing east along the access road. Vehicle traffic needs to be restricted to prevent unnecessary disturbance.

Inspection Photos



Photo 3. Facing northeast along the access road toward the location. Contractor indicated a different access point may be used due to steepness of this hill. The operator must ensure access is restricted to avoid additional disturbance.

Inspection Photos



Photo 4. Facing east toward the location.

Inspection Photos



Photo 5. Facing east along the north side of the location.

Inspection Photos



Photo 6. Facing south along the east side of the location. A soil berm is constructed around the perimeter and surface roughening has been created around the perimeter.

Inspection Photos



Photo 7. Facing northwest toward the east side of the location.